

09/932061

11-14-05

copy



Docket No.: 08211/000S107-US0  
(PATENT)

**IN THE UNITED STATES PATENT AND TRADEMARK OFFICE**

In re Letters Patent of:  
Douglas M. Hannan et al.

Patent No.: 6,943,591

Issued: September 13, 2005

For: APPARATUS AND METHOD FOR  
DETECTING A FAULT CONDITION IN A  
COMMON MODE SIGNAL

**REQUEST FOR CERTIFICATE OF CORRECTION  
PURSUANT TO 37 CFR 1.322**

Attention: Certificate of Correction Branch  
Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

Dear Sir:

Upon reviewing the above-identified patent, Patentee noted several Patent Office errors which should be corrected.

In the Specification:

Column 5, Line 36, Delete "N<sub>301</sub>," and insert - - N<sub>301</sub> - -.

Column 8, Line 45, Delete "S<sub>21</sub>," and insert - - S<sub>21</sub> - -.

Column 8, Line 46, Delete "S<sub>il</sub>," and insert - - S<sub>il</sub> - -.

Column 10, Line 17, Delete "(S<sub>3b</sub>)" and insert - - (S<sub>3b</sub>) - -.

Column 11, Line 5, Delete "S<sub>ref1</sub>," and insert - - S<sub>ref1</sub> - -.

**Certificate  
NOV 17 2005  
of Correction**

**NOV 17 2005**

Column 12, Line 11, Delete "S<sub>il</sub>," and insert - - S<sub>il</sub> - - .

Enclosed please find marked up copies of page 7, 12, 15, 16 & 18 of the Specification.

The errors were not in the application as filed by applicant; accordingly no fee is required.

Transmitted herewith is a proposed Certificate of Correction effecting such amendment. Patentee respectfully solicits the granting of the requested Certificate of Correction.

Dated: November , 2005

Respectfully submitted,

By

Flynn Barrison

Registration No.: 53,970

DARBY & DARBY P.C.

P.O. Box 5257

New York, New York 10150-5257

(212) 527-7700

(212) 527-7701 (Fax)

Attorneys/Agents For Applicant

NOV 17 2005

**UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION**

Page 1 of 1

PATENT NO. : 6,943,591  
APPLICATION NO. : 09/932,061  
ISSUE DATE : September 13, 2005  
INVENTOR(S) : Douglas M. Hannan et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Specification:

Column 5, Line 36, Delete "N<sub>301</sub>," and insert - - N<sub>301</sub> - -.

Column 8, Line 45, Delete "S<sub>21</sub>," and insert - - S<sub>21</sub> - -.

Column 8, Line 46, Delete "S<sub>il</sub>," and insert - - S<sub>il</sub> - -.

Column 10, Line 17, Delete "(S<sub>3b</sub>)" and insert - - (S<sub>3b</sub>) - -.

Column 11, Line 5, Delete "S<sub>refl</sub>," and insert - - S<sub>refl</sub> - -.

Column 12, Line 11, Delete "S<sub>il</sub>," and insert - - S<sub>il</sub> - -.

MAILING ADDRESS OF SENDER:  
Flynn Barrison  
DARBY & DARBY P.C.  
P.O. Box 5257  
New York, New York 10150-5257

1

NOV 17 2005



Application No. (if known): 09/932,061

Attorney Docket No.: 08211/000S107-US0

## Certificate of Express Mailing Under 37 CFR 1.10

I hereby certify that this correspondence is being deposited with the United States Postal Service as Express Mail, Airbill No. \_\_\_\_\_ in an envelope addressed to:

**EV 692134356-US**

Attention: Certificate of Correction Branch  
Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

on November 10, 2005  
Date

*B.W. Lee*

Signature

**B.W. LEE**

Typed or printed name of person signing Certificate

Registration Number, if applicable

Telephone Number

Note: Each paper must have its own certificate of mailing, or this certificate must identify each submitted paper.

Certificate of Correction (1 page)  
Request for Certificate of Correction (2 pages)  
Marked up copies of the specification (5 pages)  
Return Postcard

NOV 17 2005